Common Performance Tasks - Geekbench 7

Highest Performance Modes, Higher is Better




Max CPU Performance - Cinebench 2026 Single Run

Highest Performance Modes, Higher is Better




Power Draw - Cinebench 2026

Highest Performance Modes, Lower is Better




CPU Core Temperatures - Cinebench 2026

Highest Performance Modes, Lower is Better




Hottest Surface Temperatures - Cinebench 2026

Highest Performance Modes, Lower is Better




Fan Noise - Cinebench 2026

Highest Performance Modes, Lower is Better




Weight

Lower is Better




Timespy

Highest Performance Modes, Higher is Better




Display - Max Brightness

Higher is Better



Battery Rundown - Office Tasks

300 Nits, Wi-Fi & Bluetooth On - Higher is Better



Performance on Battery

Cinebench 2026 Single Run - Higher is Better



3DMark - Steel Nomad Light

Highest Performance Modes, Higher is Better

